
AQU • PLANK®







MORNINGTON

ignature laminates

AQU • PLANK°

MORNINGTON



MORNINGTON1160 Wilson Spotted Gum



MORNINGTON1161 Jacana Spotted Gum



MORNINGTON1162 Beleura Spotted Gum



MORNINGTON1163 Bayview Blackbutt



MORNINGTON1164 Nelson Blackbut

TECHNICAL SPECIFICATIONS

Plank Size 166 x 1210 x 8mm Edge Design V groove 4 sides

Finish Matt Power-Seal™all edges Wear Layer Treatment Clear enhanced UV cured coating Wear Class AC4 commercial-grade quality

Core Ultra Stable SureCore™ - provides 60% more stability

Technology AtroGuard™ 'Water-Resist' Technology

Planks per Box 11 pcs/box (2.21m²) Features Superior pattern repeat

Impact, indent, stain, scratch & water resistant

Slip, fire, wear & fade resistant Suitable all areas (>4.5kW/m² CRF)

Installation Tight Lock™- minimum sub-floor preparation required*

> Install up to 400m² without transition strips Install in dry & wet areas - see installation guides

Heating Suitable for underfloor heating Environment Contains 0% plastic elements

Warranty Lifetime Residential, 12 Yr Light Commercial











Fire Rating































au 03 9401 0888 **nz** 0800 150 555 signaturefloors.com.au signaturefloors.co.nz

Terms & Conditions: Specifications are subject to manufacturing tolerances and may be changed without prior notice. Dye lots may vary in colour from sample and between production lots. All product purchases are subject to Signature Floorcoverings Standard Terms & Conditions of Sale. Please refer to our Installation Guideline, Maintenance Manual and Warranty Document for further clarification. This warranty is in addition to and does not affect your statutory rights. Our goods come with guarantees that cannot be excluded under the Australian Consumer Law/NZ Consumer Guarantees Act 1993. You are entitled to a replacement or refund for a major failure and compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.