

# THE ENDURING BEAUTY OF WOOL



# 100% undyed wool

## reed



reed palomino 103



reed jerboa 104



reed merle 105



reed quokka 106



reed brindle 109



reed marmot 112

- |                        |                                  |
|------------------------|----------------------------------|
| fibre                  | • 100% undyed wool, 4 ply/12 ply |
| fibre weight           | • 70oz (2550gsm)                 |
| pile height            | • 11mm                           |
| construction           | • sisal                          |
| gauge                  | • 5/16                           |
| backing                | • hessian                        |
| surface treatment      | • insect resistance              |
| width                  | • 4m                             |
| fire rating ISO 9239.1 | • >4.5kw/m <sup>2</sup> CRF      |



wear



defect



insect  
resistance



au 03 9401 0888  
nz 0800 150 555  
[signaturefloors.com.au](http://signaturefloors.com.au)  
[signaturefloors.co.nz](http://signaturefloors.co.nz)

\*Products featured on cover (clock-wise) Jaro Suelo 107, Coco Lana 101, Nobby Nigella 116, Coco Lana 101, Jaro Nuebe 110 and Suelo 107

**Terms & Conditions:** Specifications are subject to manufacturing tolerances and may be changed without prior notice. Dye lots may vary in colour from sample and between production lots. All product purchases are subject to Signature Floorcoverings Standard Terms & Conditions of Sale. Please refer to our Installation Guideline, Maintenance Manual and Warranty Document for further clarification.

This warranty is in addition to and does not affect your statutory rights. Our goods come with guarantees that cannot be excluded under the Australian Consumer Law/NZ Consumer Guarantees Act 1993. You are entitled to a replacement or refund for a major failure and compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.